

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Robert L. Morgan **Executive Director** Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone

(801) 359-3940 fax

(801) 538-7223 TTY

www.nr.utah.gov

INSPECTION REPORT

Partial: XXX	Complete:	Exploration:
		2002 / 1:00 pm -4:00 pr
r		st Inspection: 07/31/200

Mine Name: Gordon Creek 2, 7, & 8 County: Carbo	on Permit Number: <u>C/007/016</u>
Permittee and/or Operator's Name: Mountain Coal Cor	npany
Business Address: HC 35 Box 380, Helper, Utah 8452	5
Type of Mining Activity: Underground XXX	Surface Prep. Plant Other
Company Official(s): Dan Guy, Vicky Miller	
State Official(s): Joe Helfrich	Federal Official(s): None
Weather Conditions: Sunny, 80	
Existing Acreage: Permitted 180 Disturbed 20	.3 Regraded Seeded Seeded
Status: Active Reclamation XXX	<u>-</u>

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]		[X]	\Box
3.	TOPSOIL				\Box
4.	HYDROLOGIC BALANCE:	·			
a.	DIVERSIONS	\Box			\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES				
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS	\Box	\Box	[X] [_]	\Box
5.	EXPLOSIVES	\Box	[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ĺ	[X]		\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]	\Box	\Box
8.	NONCOAL WASTE	\Box	[X]		\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	\Box			
10.	SLIDES AND OTHER DAMAGE	\Box			
11.	CONTEMPORANEOUS RECLAMATION	\Box			
12.	BACKFILLING AND GRADING		[X]		
13.	REVEGETATION	\Box	\Box	\Box	
14.	SUBSIDENCE CONTROL		[X]		
15.	CESSATION OF OPERATIONS		[X]		
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	[X]		
b.	DRAINAGE CONTROLS		[X]		
17.	OTHER TRANSPORTATION FACILITIES		[X]	\Box	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	[X]		
19.	AVS CHECK (4th Quarter- April, May, June)		[X]	\Box	
20.	AR TAILT PERMIT		\Box		
21.	BONDAY & INSURANCE Where ideas connect	\Box	\Box	\Box	

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/016

DATE OF INSPECTION: 08/21/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

There are two amendments pending, #BR01B, Phase I bond release. The response to the TA was received August 2, 2002 and is scheduled for review on September 13, 2002 and #AM02A, (Rock Gabion removal) submitted on March 13, 2002. The amendment was reviewed by Division staff (Joe Helfrich and Dave Darby). The TA contained one deficiency. That deficiency was **R645-301-731 and 752.220**, the applicant was required to demonstrate that no additional contributions of suspended solids were occurring in the receiving stream channel and prevent material damage outside the permit area.

2. SIGNS AND MARKERS

The identification sign located at the main access at the end of the county road was legible and in good repair.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

On the day of this inspection, the three-celled pond was in good repair and functioning properly. The site has remained unchanged since the previous inspection.

4D. HYDROLOGIC BALANCE: WATER MONITORING

During the inspection, Dan, Vicky, and I discussed sampling locations for the reclaimed fan portal area. The Division has requested that the operator demonstrate that the reclaimed area can meet the effluent of the reference area and not impact receiving waters outside the reclaimed area. The drainage just below the reference area, the lower end of the diversion ditch below the reclaimed fan portal area, and the diversion ditch down stream from the reclaimed area before it enters the North Fork of Gordon Creek were selected as possible sampling locations. To date, there has not been an opportunity to obtain a sample from any of the suggested locations. We discussed the option of installing a rain gauge on or near the site to provide data that may help demonstrate no off site impacts. I offered to discuss this concept with Dave Darby and Daron Haddock.

Inspector's Signature:

oséph C. Helfrick #

Date: August 23, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chris Hansen, Canyon Fuel Company Vicky Miller, Canyon Fuel Company Dan Guy, Blackhawk Engineering

Price Field office

O:\007016.GC2\COMPLIANCE\2002\P_0821.DOC